

Hydrant Inspection Report

Docket No. 01-0490

ICC Staff Exh. 1.02

pg. 1 of 2

McHenry Shores Water Company

	1997	2001	
Location	Gals. per min.	Gals. per min.	Comments
Wellhouse on Hilltop Blvd.	1060	No flow test	a) Repair nozzle cap chains; and
			b) Hydrants requires painting.
Bonita & Beach	1170	1190	a) Hydrant requires painting; and
			b) Increase height of hydrant (18" to middle of Cap)
Hollywood & Vine St.		No flow test	Repalce does not work. [Operated by Hydrant valve.]
Vine and Green St.	920	400	a) Repair: Hard to operate [restricted flow];
			b) Hydrants requires painting; and
			c) Repair nozzle cap chains.
Biscayne Rd. & Carey	840	880	a) Hydrants requires painting.
Forrest Rd.	820	840	a) Hydrants requires painting.
			b) Increaser hieght of hydrant (18" to middle of cap.)*
Forrest Rd. & Hollywood	890	920	a Hydrants requires painting.
Pleasant & Bonnie	550	590	a Hydrants requires painting.
Pleasant & Broadway	550	550	a) Hydrants requires painting.

No Change from last inspection

Hydrant Inspection Report

Docket No. 01-0490

ICC Staff Exh. 1.02

System: **McHenry Shores Water Company**

pg. 2 of 2

		1997	2001	
Hydrant #	Location	Gals.per min.	Gals.per min.	Comments
20	Capri - about middle of block	560	No flow test	a) Hydrant requires painting.
16	Broadway & Hunter Path	600	600	a) Rpalce hydrant due to crack upper barrel.
14	Broadway & Vista Terr.	710	790	a) Hydrant requires painting; and
7	Hilltop & Vista Terr.	710	725	a) Rpalce hydrant due to crack upper barrel.
8	Still Hill Dr. & near Pearl Ave.	420	400	a) Increase height of hydrant (18" to middle of Cap); and b) Hydrant requires painting.
9	Still Hill Dr. & near Riverside Dr.	480	No flow test	a) Hydrant requires painting; and b) Repair hydrant nozzel caps.
6	Riverside Dr. & Miller Dr.	480	450	a) Hydrant requires painting.
Flushing Valves				
21	Hilltop	20	20	a) Remove copper tubing and replace with hydrant.
24	3216 Beach	300	200	
22	Pearl & Broadway	420	420	a) Install flushing hydrants.
23	Pearl & Carol	420	420	a) Install flushing hydrants.
27	805 Broadway	400	420	

Note: No Change from last inspection